

ACCORD

on Fire and Building Safety in Bangladesh

Date: 14/12/2017

Subject: Accord Structural Safety Assessment for United Fashion Trouser Ltd. (10828)

For the attention of Factory Owner/Manager, Lead Brand, Active Brands & Union Colleagues,

We are writing to inform you as the Accord active and responsible brands at below factory.

*Factory Name: United Fashion Trouser Ltd. (10828)
Address: Chaydana, P.O. National University, Gazipur.*

The Accord conducted an initial structural assessment at this facility on 21/06/2014. The Accord also conducted Follow-up structural inspections last on 21/11/2017.

The factory has completed remediation on all structural issues identified in the Accord initial structural inspection report for this factory. Any colour category associated with this factory is no longer valid, and the Accord is satisfied that general compliance with our structural safety standard is achieved.

Please note that this clearance is given based on the inspections conducted by the Accord and does not cover any modifications, extensions etc. which have taken place after the initial inspection, unless specifically verified by the Accord. The factory must ensure the on-going compliance with loading plans and maintenance to ensure the integrity of the building. The Accord reserves the right to add further structural findings in the future.

This letter is reference to structural findings only. It does not reference fire and electrical findings.

Sincerely,

*Rob Wayss
Executive Director & Acting Chief Safety Inspector
Stichting Bangladesh Accord Foundation*